

Figure 2.14 - Vertical gas atomisation (schematically)

## ATOMIZAÇÃO A GÁS (AR):

- Ao ar (Al, Cu e suas ligas, metais preciosos, Sn, Pb, ...);
- A gás inerte: todas as ligas principalmente as de alto teor (aços, superligas, ...).




Figure 2.18 Atomised iron powders resulting from water atomisation (a), (b), gas atomisation (c), rotational atomisation (d)