



Densification during compaction by changes in particle arrangement and shape



Cold pressing principles (left: axial- resp. die-pressing; right: isostatic pressing)



Tooling for axial hot pressing. a) induction heating; b) direct current heating; c) convection/radiation heating

