




THE PHYSICAL CHEMISTRY OF IRON- AND STEELMAKING



DIA GRAMA, DE ELLINGHAM - RICHARDSON

Fig. 10 - The free energies of formation of oxides for the standard states: pure elements, pure oxides and gases at 1 atm.